

Missouri summers make a functioning air conditioning system essential rather than optional in any vehicle. When your A/C stops blowing cold, blows cold only intermittently, or produces unusual odors, A Auto Express in Raytown diagnoses and repairs automotive air conditioning systems for all makes and models across the Kansas City metro. The most common cause of A/C failure is refrigerant loss. The A/C system is a closed loop that should retain its refrigerant charge indefinitely. When the system loses refrigerant, the leak must be identified and repaired before recharging. Simply adding refrigerant without finding the leak produces temporary improvement that fades as the refrigerant escapes again. A Auto Express performs A/C system leak detection using UV dye or electronic leak detectors, identifies the source, repairs it, and then recharges the system to the correct specification for your vehicle. The correct refrigerant type and charge amount are specific to your vehicle's [Auto Repair Raytown](#) system, and filling to the right level is as important as filling at all.

A Auto Express Auto Repair Raytown | 6140 Blue Ridge Blvd, Raytown, MO 64133 | +1 816-503-6153



A Auto Express Auto Repair

Auto Repair Raytown

6140 Blue Ridge Blvd, Raytown, MO 64133

+1 816-503-6153

Graphite White

Auto Repair Raytown

A/C compressor failure is the most expensive common A/C repair. The compressor pressurizes the refrigerant. When it fails, it often circulates metal debris through the system. A proper compressor replacement includes flushing the system to remove contamination before installing the new unit, preventing premature failure of the replacement. Other A/C system components including the condenser, evaporator, expansion valve, and blower motor all have specific failure modes that A Auto Express <https://anotepad.com/notes/p2a6tmm5> mechanics diagnose and address. Raytown summers with temperatures regularly reaching the high 80s and 90s make working A/C a daily necessity for comfortable and safe driving. A hot vehicle interior affects driver alertness on long commutes. For A/C diagnosis and repair in Raytown, call A Auto Express at +1 816-503-6153. Monday through Friday, 8 AM to 5 PM.